UNCLASSIFIED

AD NUMBER AD147191 CLASSIFICATION CHANGES TO: UNCLASSIFIED FROM: RESTRICTED LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited. Document partially illegible.

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;

Administrative/Operational Use; 30 SEP 1945. Other requests shall be referred to Frankford Arsenal, Philadelphia, PA. Document partially illegible.

AUTHORITY

E.O. 10501 5 Nov 1953 ; FA ltr 25 Mar 1975

AIMINGLASSIFIED AIMINGLASSIFIED AIMINGLASSIFIED AIMINGLASSIFIED AIMINGLASSIFIED

Armed Services Technical Information Agency

DOCUMENT SERVICE CENTER KNOTT BUILDING, DAYTON, 2, 0 HIO


FOR
MICRO-CARD
CONTROL ONLY

1 OF 1

NOTICE: WHEN GOVERNMENT OR OTHER DRAWINGS, SPECIFICATIONS OR OTHER DATA ARE USED FOR ANY PURPOSE OTHER THAN IN CONNECTION WITH A DEFINITELY RELATED GOVERNMENT PROCUREMENT OPERATION, THE U. S. GOVERNMENT THEREBY INCURS NO RESPONSIBILITY, NOR ANY OBLIGATION WHATSOEVER; AND THE FACT THAT THE GOVERNMENT MAY HAVE FORMULATED, FURNISHED, OR IN ANY WAY SUPPLIED THE SAID DRAWINGS, SPECIFICATIONS, OR OTHER DATA IS NOT TO BE REGARDED BY IMPLICATION OR OTHERWISE AS IN ANY MANNER LICENSING THE HOLDER OR ANY OTHER PERSON OR CORPORATION, OR CONVEYING ANY RIGHTS OR PERMISSION TO MANUFACTURE, USE OR SELL ANY PATENTED INVENTION THAT MAY IN ANY WAY BE RELATED THERETO.

UNCLASSIFIED

Best Available Copy



UNCLASSIFIED

REPORT NO. R-627

HIGH SPEED X-RAY PICTURES OF THE FUNCTIONING OF 20 MM H.E.I. SHELL M 97 (T23) WITH FUZE P.D. T71E4

FIRST REPORT

PROJECT:2/148

PREPARED BY:

EDWARD R. T. ILO Physicist

REVIEWED BY:

HERSCHEL SMITH Physicist

C. C. FAWCETT Assoc. Director of Laboratory

APPROVED BY:

C. H. GREHALL Lt Col, Ord Dept Director of Laboratory

FOR:

J. B. ROSE Colonel, U. S. Army Communding

pb

UNCLASSIFIEL

RESTRICTED



To take a series of high speed X-ray pictures showing the functioning of 20mm H. E. I. Shell M97 (T23) similar to the studies carried out for the 20 mm H.E.I. Shell MK-I.

SUMMARY

A series of high speed X-ray pictures have been taken which show the functioning of 20mm H.E.I. Shell M97 (T23) with Fuze P.D. T71E4 when fired through the following thickness of target plates: .012 in., 1/16 in., .083 in., 1/8 in. and 1/4 in. The pictures show the time of function, the manner of fragmentation of the shell and the formation of the hole in the plate.

At a striking velocity of approximately 2850 f/s against target plates placed normal to the line of fire the functioning of the shell is dependent on the thickness of the plate. Against .083 in. plate all shells functioned while passing through or after having passed through the plate. When fired against 1/8 in. and 1/4 in. plates the shells consistently functioned and ruptured before the bourrelets of the shells had passed through the plate. None of the shells fired against the .012 in. plate functioned. When fired against the 1/16 in. plate the shells frequently did not function until they were completely through the plate. Two shells out of 20 fired did not function at all.

The dependence of the functioning of the shell on the angle of impact and on velocity was observed on .083 in plates. When fired at a striking velocity of approximately 2850 f/s against the plate inclined at 20° to the line of fire all shells functioned consistently and ruptured before having passed half way through the plate. Against a plate placed normal to the line of fire the shells frequently passed completely through the plate before functioning.


When fired at 1600 f/s against the plate placed normal to the line of fire eight shells out of 35 fired did not function at all.

The shells swell to almost twice normal diameter before rupture is visible.

The explosion imparts a radial velocity of approximately 2000 f/s to the shell fragments.

AUTHORIZATION

00 1.71.1/25916



I. INTRODUCTION

UNCLASSIFIED

This Arsenal has taken high speed X-ray pictures which show the functioning of 20 mm H.E.I. Shell MK-I, with Fuze No. 253 MK-II, when fired through a mild steel target (1/16 in. and 1/8 in. thick) placed normal to the line of fire. The pictures show the manner in which the shell ruptures and the formation of the hole in the target plate. (1) A request was received from the Office Chief of Ordnance to conduct similar studies for the 20 mm H.E.I. Shell M97 (T23). (2)

II. METHODS

A. Weapon

A 20 mm gun tube AN-M2 was used for the firing. An adapter sleeve was screwed on the breech end of the tube. This sleeve was threaded for the "A.E.S." screw-on firing action permitting convenient single round firing.

B. Ammunition

20 mm H.E.I. Shell M.97 (T23) with Fuze P.D. T71E4 were used for these tests. A stationary radiograph of this shell is shown on Figure 1.

C. Targets

Mild steel plates (WD 1010 hot rolled annealed and pickled, or cold rolled, dead soft temper) were used as targets. The following target plates were used:

- (1) .012 in. \times 12 in. \times 16 in. placed normal to the line of fire.
- (2) 1/16 in. (.063 in.) x 12 in. x 16 in. placed normal to the line of fire.
- (3) .083 in. \times 12 in. \times 16 in. placed normal to the line of fire.
- (4) .083 in. \times 12 in. \times 36 in. inclined at 20° to the line of fire (70° between the trajectory and the normal to the plate).
- (5) 1./8 in. (.125 in.) x 12 in. x 16 in. placed normal to the line of fire.
- (6) 1/4 in. (.250 in.) x 12 in. x 16 in. placed normal to the line of fire.

The shells were first it striking velocity of approximately 2650 f/s through each of the above tirrits and also at reduced velocity (1600 f/s) through the .003 in. target placed normal to the line of first. A new target plate was used for each shot. The target was located 25 ft. from the muzzle of the run.

* 1 171.1/2591

RESTRICTED

[&]quot;Frankford Armenal Oranshoe Lateratory hosert No. h-186, "High Speed A-m y Fectures of 10 cm h.E.i. Shell EX-19 by E. m. Thile

D High Speed X-Ray Pictures

The high speed X-ray equipment (3) was used in taking the pictures. A picture showing the arrangement of the X-ray tubes and film with respect to the target and fragment protection is shown on Figure I of Frankford Arsenal Ordnance Laboratory Report No. R-480.(4)

A number of shells were fired through each thickness of plate and high speed X-ray pictures were taken at the instant of impact and at varying times thereafter.

For the targets placed normal to the line of fire two mutually perpendicular high speed X-ray pictures were taken of the functioning of each shell. A diagram of the set-up used in taking these pictures is shown on Figure 3 of Frankford Arsenal Ordnance Laboratory Report No. R-480. (5) The line of fire was varied from 2 in. to 4 in. above the horizontal film cassette. Maximum detail of the functioning of the shell was obtained on this horizontal film. The mutually perpendicular picture was taken on the vertical film. This film was located 9 in. from the line of fire and the pictures obtained on this film are lacking in detail. However the failure of a shell to function such as round 18 on Figure 5 was revealed by this vertical picture.

In the case of the .083 in. target inclined at 20° to the line of fire only a single high speed X-ray picture was taken of the functioning of the shell. The horizontal tube and film cassette arranged as shown on Figure 3 (side view) of Frankford Arsenal Ordnance Laboratory Report No. R-480 (6) were used.

All high speed X-ray pictures were taken at 360 kilo-volt peak and using Patterson #245 industrial combination intensifying screens with Eastman Plue Brand Ultra Speed X-Ray Film.

III. RESULTS AND DISCUSSION

Representative prints of the X-ray pictures are shown on the figures that follow. These were selected from a large number of pictures not have in a produced. The descriptive material accompanying the pictures is based on an examination of the original negative and some of the details have been lost in the reproduction process.

⁽³⁾ Frankford Arsenal Ordnance Inboratory Report No. R-189, "High Speed λ -key Equipment" by E. R. Thilo and C. M. Hudson

⁽a) hef. 1. loc. cit.

⁽⁵⁾ R.f. 1, loc. cit.

^{(4) 1014.}

The pictures shown on Figures 2, 5 and 19 are direct prints from the X-ray negatives. The pictures shown on Figures 3, 4, and 6 to 18 inclusive have been copied from direct prints made from the X-ray negatives. The copied pictures have been reduced to approximately 1/3 size.

Figure 18 is included for comparing the manner in which the 20 mm H.E.I. Shell MK-I functions.

Two high speed X-ray pictures showing the fragmentation of 20mm H.E. Shell MK-III (Navy) (7) are shown on Figure 19.

Figure 5 shows two mutually perpendicular high speed N-ray pictures of one shell exploding with a time interval of approximately 44 microseconds between pictures. The average radial velocity imparted to the fragments by the force of the explosion was approximately 2800 f/s. This value agrees well with the values reported by Major Clark of Aberdeen. (8)

The X-ray pictures correlated with observations of the target plate revealed the following facts. Except where otherwise indicated the shells were fired at service velocity against target plates placed normal to the line of fire.

- (1) .Ol2 in. target plate (Figure 2)
 (a) The shells did not function when fired through this thickness of plate.
- (b) The windshields of the shells were not crushed up as a result of the impact.
- (2) 1/16 in. (.063 in.) target plate (Figure 3,4, 5)
 (a) The shells frequently did not function until
 they were completely through the plate. Two shells out of 20
 fired, did not function at all.
- (b) The shalls which did function while passing through the plate ruptured when more than half way through. This resulted in only small holds (2 1/8 in. maximum diameter) being formed in the plate.
- (c) The 20 mm H.E.I. Shell EK-I (Fuze #253, MK-1) when fired through the same thickness of plate all functioned. Rupture of the shells consistently occurred before the shells had passed here than half way through the plate. A hole approximately Line in director was formed in the plate. (9)

to frust reseased for the descriptory aspect to as 190, is not to

⁽⁷⁾ Frankford Aracial Ordnance Labor tory Report Ma-70, "High Speed X-Ray Pictures of the Functioning of 20 mm H.E. Small Ak-H1 (Novy) show Fired Through 1/8 in. Fild Steel Torget Flood Serial to the Line of Fire , by E. S. Thilo

⁽F) At orders Freving Or und Bullistic & search i burning Aspert No. 5.9. "Fl at Mull ar the of \$ 11, 10mm H.T.I. ML-1 During St tie Deter time ty h p r J. 3. 31 rk

- (3) .083 in. target plate (Figure 6, 7)
- (a) All shells functioned when fired through this thickness of plate.
- (b) The time at which the shells functioned varied. Eight shells out of 32 fired passed completely through the plate before functioning.

Ť

-

- (c) Shells which functioned and ruptured before passing half way through the plate produced large holes (6-7 ins. in digmeter). The momentum imported to the petals on the back of the plate from the force of the explosion caused them to curl back and form the large hole.
- (4) .083 in. target plate, shall fired at reduced velocity (1000 f/s)/Figure 8,9).
- (a) Thirty-five shells were fired at reduced velocity through this thickness of plate. Two shells functioned after passing through the plate. Eight shells did not function at all.
- (b) The other 25 shells functioned. Rupture of these shells consistently occurred before the shells had passed more than helf we through the plate. These shells produced a large h le (6-7) in diameter) in the plate.
- (5) .083 in. target plate inclined at 20° to the line of fire. (Figure 10, 11)
- (1) The shells all functioned consistently and ruptured before having passed half way through the plate.
- (b) The explosion of the shells produced a hole approximately 2 3/4 in. in diameter in the plate. The momentum imparted to the petals on the back of the plate from the impact of the mushroomed shell base caused them to curl back and form a much larger hole (4 1/2 ins. in diameter)
 - (6) 1/8 in. (.125 in.) target plate. (Figure 12, 15, 14)
- (a) The shells all function before passing through the plate.
- (b) The shells start to swell approximately 74 microactions after impact. Repture of the shells takes place before the bourselets of the shells have passed through the plate (approximately 45 microsums in after impact).

RESTRICTED

- (c) The momentum imparted to the petals on the back of the plate from the force of the explosion caused them to curl back and form a large hole (6-7) in. in diameter).
- (d) The 20 mm H.E.I. Shell MK-I (Fuze #253, MK-II) functioned in a similar manner when fired through the same thickness of plate. (10)
 - (7) 1/4 in. (.250 in.) target plate. (Figure 15, 16, 17)
- (a) The shells all functioned before passing through the plate.
- (b) The shells start to swell approximately 20 microseconds after impact. Rupture of the shells takes place before the bourrelets of the shells have passed through the plate (approximately 40 microseconds after impact).
- (c) The momentum imparted to the petals on the back of the plate from the force of the explosion caused them to curl back to form a hole approximately 5 in. in diameter.

The shells swell to almost twice normal diameter tefore visible rupture takes place. The noses of the shell breaks up into fragments. In the case of the H.E.I. MK-III shell the noses of the shells remained in one fince. The fragment tion of the rest of the shells is similar to that of the MK-III shells (i.e. rupture of the shell body, mushrooming out of the base of the shell).

The fragmentation of the Lemm H. E. Shell, Mk-III(K-v;), is different from the H. E. I. Shell in that the nose, body and base of the shelle all break up into small fragments when the shells ru; ture.

IV CONCILISATION

1

The high speed Z-ray pictures show the manner in which the shall function, the frament tion pattern of the shall and the formation of the hold in the plate.

At striking valocity of a roxiditely 1850 1/2 a limit to rate places placed normal to the line of fire the function income of the chall is dependent on the thicks as of the plate used. Against 1850 in. triangle to the hells functioned unite presing through or after a variety and through the plate. Then fired against thick rapid to the shells consist atty functioned and ruptured before the consist atty functioned and ruptured before the plate.

The impact or the soil is a consume or the med of appet. It finds to traking a locality of a rowin toly of a solid life in the first of the constitution of the life in the first of the constitution of constitution and supplies to the law and prove the plate. As a soil to plate the result of the life in th

fire the shells frequently passed completely through the plate before functioning. The functioning of the shell is also dependent on the striking velocity. Then fired at a striking velocity of approximately 1600 f/s against the plate placed normal to the line of fire eight shells out of 35 fired did not function at all.

In order to form a large hole in the plate the shell must function and rupture before it has passed more than half through the plate.

V. RECOMMENDATIONS


It is recommended that in the development of 20 mm Incendiary, H.E.I., and H. E. Shells that the functioning of these shells be studied by means of high speed X-ray pictures.

RESTRICTED

Initial distribution of this report:

- 1 Commanding Officer
 Picatinny Arsenal
 Dover, New Jersey
 Attn: Technical Group
- 1 Commanding Officer
 Rock Island Arsenal
 Rock Island, Illin is
 Attn: Technical Group
- 1 Communding Officer
 Springfield Armory
 Springfield, Mass.
 Attn: Engineering Dept.
- 1 = Communding General
 Abordeen Proving Ground
 Abordeen, Maryland
 Attn: Billistic Resourch Labor tory
- 1 Commanding Cificer
 Wittert wn Arsen 1
 Wittert wn, action
 Attn: Technic 1 Gr up
- 7 Army Service Fires Office Chief of Ordnance Washingt n., 25, D. C. Attn: SPOTE - Technical Reports
- 1 Army Survice Fires
 Office Shief if Ordninge
 Washington, 25, D. C.
 Attn: SPCTM Art. Arm. Fr.
- 1 Arg Service Frees Office Chief of Orwance Jushimatin, 19, 5. C. Attn: 37011
- 1 Arty 3 rvio F reso Office Shief for in nes a shiest n. 15, 5. 5. Attr: SFCT3

RESTRICTED



Stationary X-Ray Picture of 20 mm. H.E.I. Shell M 97 (T 23) With Fuze P.D. T 71 E 4

- 1 Detonator, Approximately 5.8 grains Mercury Fulminate
- 2 Lower Detonator, Approximately 2.69 grains Leed Axide
- 3 Magazine Charge. Approximately 2,9 grains Tetryl
- 4 Tetryl, Approximately 83.4 grains Tetryl
- 5 Incendiary Composition, Approximately 34.0 grains


MEG. #1585.1

1

FIGURE 1


9 JUNE 1944

High Speed X-Ray Pictures of the Functioning of 20 mm. H.E.I. Shell M 97 (T 25) when fired through an .012 in. mild steel target placed normal to the line of fire. Fuze P.D. T 71 E 4.



NEG. #15859-2 FIGURE 2 9 JUNE 1.945

9 / NE . 145



/ . % = ± 0%0

High Speed X-Ray Pictures of the Functioning of 20 mm. H.E.I. Shell M 97 (T 23) when Fired through a 1/16 in. mild steel target placed normal to the line of fire. Fuze P.D. T 71 K 4



rependicular picture of this shell taken approximately 44 microseconds later.

NET OF AINDHIELD IN COMPACT AIRM THE FLATS


THE NOTE OF THE CHELL HAD ACCEDED THE TOP THE PLATE. THE WINDOMEDIA HAD EXPEDIENCED ASSESSION OF CRETE HER.

THE CHELL BODY HAS SWELLED TO DOES TAILS AS MAN DIAMSTER AND BUFFLED. THE DETAIL HAS CONTRACTED THE BOURRELST REGION OF THE CHELL HOW CARLLING AS RAPIDLY AS THE BODY OF THE CHELL THE BASES OF THE CHELL HAS SWELLES MEDICAL

THE CHELL BODY HAT STARTED TO SWELL

THE BACK OF THE CHIRL HAT VICTOR DWT TO THE SERVICE AND CHIRL HE SERVICE

75.1 F & 80%*



FIRRE 6

· 🕠

K\$3. \$15604-1

9 7 NX 1/45

THE PRAGMENT OF THE BASE OF THE SHELL ARE PASSING THROUGH THE HOLE.

THIS SHELL PASSED COMPLETELY THROUGH THE FLATE HEFORE IT FUNCTIONED. NO PETALS HERE FORMED IN THE PLATE.

湯

THE THEEL PRACMENTS ASSESSMENT AS COMPOSITION OF THE PROPERTY OF THE ASSESSMENT ASSESSMENTS.



THE NOTE OF THE CHE. HAS BROKEN THE ONLY THE PROPERTY OF

Begins 160 . The financials has given some a consum CF of 100


WITALLY INHERDICALAR FITTING OF HARD INCOMPEN AFFR KINATSIA, A WITHOUTER OF LATER THE CHE. TILL HAS NOT PROGRESS. THE TILL OF THE AIRCE OF THE HAS HARDEN OF

THE WINDHIELS HAT EXPENSENCED MEN SITTLE BOTH OF THIS THEE, DIS NOT FIRSTERS

THREE TO USE BEY BY FIATE

which will be the line of the

Mark the second second



MM). /15684-3

FIGURE 6

9 JUNE 1945

HIGH CIRES Y-HAV PICTIAET OF THE FUTULINING OF STAW, H.F. THES. MOS. T. F. WHEN THEM AT RESERVE MELOCITY (16 K. T.S. THEOLOGY A. W. Y. Y. Y. THE TAROTT HASE MORMAL TO THE LINE & SIFE F. E. H. T. L. E. 4

178

NEG. \$15684-4

9 e en 1

THE RIGHT OF THE CURL, TO REEAVING IT INTO PRACMETER.

FICKER 9

9 JUNE 1945

NOCE OF THE WINDSHIELD IN CONTACT ALTS THE PLATE

THE WINDSHIELD HAS SYMBLENGED CONSIDERABLE OF THE LP. THE SHELL BODY HAS SWELLED TO ALMOST TWICE NOWALL DIAMETER. THE FITS OF THE SHELL WAS TREED WERE LISTER.

THE CHELL HAS MUSTICALL. THE BACK OF THE CHELL IS THAT THAT IN TO MUSTHAND OF THE CHELL I KAGMENT ON THE BACK CIES OF THE CLAIR ALE CONTINEANS! IN THE BACK ALL AND FARMAD MOTION OF THE LIAME FETTICS.





NKG. #15021

No.

FICURE 11

9 JUNE 1945

THE STREET OF TH


9 JUNE 1945



FIGURE 15

9 JUNE 1945

NR J. #150/10-2



THE PETALS HAVE CURLED BACK TO PRODUCE A HOLE APPROXIMATELY 54 IN. IN DIAMETER.



THE GEOMETRIC PROTESS HAVE LEGISLATED BY THE HUNCELD HIM OF 20 MM. H.E.I. THE LAW OF , I are HERE FIND THEORY A. A. A. IN. MILD THE LEGISLATED AT LABOUR LEGISLATED BY A LABOUR LEGISL

KRG. /15155-1

FICKER 15

9 JUNE 1945

HIGH SPEED X-RAY PICTURES OF THE FUNCTIONING OF 20 LM. H.E.I. SHELL M 97 (T 23) WHEN FIRED THROUGH A 1/4 IN. MILD STEEL TARGET PLACED NORMAL TO THE LINE OF FIRE. FURE PD T 71 E 4

And a management of standard and a management of standard and standard

* 1.2



9 JUNE 1945

HIGH SPEED X-RAY PICTURES OF THE FUNCTIONING OF 20 MM. H.E.I. SHELL M 97 (T 23) MHEN FIRED THROUGH A 1/4 IN. MILD STEEL TARGET PLACED NORMAL TO THE LINE OF PIRE. FIRE OF THE ACCOUNTY OF THE ACCOUNTY OF THE NEW OF THE PARTY OF



KEG. #15155-3

FICKER 17

9 JUNE 1945

- AND THE RESERVE ASSESSMENT OF THE PROPERTY O

HIGH SPEED X-RAY PICTURES OF THE FUNCTIONING OF 20 MM H E I SHELL MK I WHEN FIRED THROUGH A $\frac{1}{8}$ IN MILD STEEL PLATE PLACED NORMAL TO THE LINE OF FIRE

THE NUSE OF THE SHELL HAS PASSED THROUGH THE PLATE THERE HAS BEEN NO SHIFT OF THE DETONATING PARTS OF THE FUZE

THE SHELL HAS STARTED TO SWELL IN THE REGION OF THE BOURRELET. THE BOOSTER HAS NOT YET DETONATED

THE SHELL HAS SWELLED MUNE THAN THE SHELL PICTURED IN D. THE MAXIMUM SWELLING IS STILL IN THE REGION OF THE HOURHELET. THE BOOSTER HAS DETONATED THE RING OF PETALS ABOUT THE SHELL CAN BE SEEN.

THE SHELL BODY HAS SWELLED TO ALMOST TWICE NORMAL DIAMETER THE PETALS HAVE CONSTRAINED THE BOURRELET HEGEN OF THE SHELL FROM SWELLING AS RAPIDLY AS THE BOOK OF THE SHELL THE HASE OF THE SHELL HAS SWELLED ZERY __TTILE.

THE SHELL HAS MUPTURED THE BASE OF THE SHELL IS STARTING TO MUSHROKAM OUT. THE CONSTRAINING EFFECT OF THE PETALS IS EVIDENT.

THE HASE IF THE SHELL HAS MUSHRISMED OUT EVEN FURTHER THE MUSE AND JOHN THE THE SHELL FRAGMENTS HAVE PASSED OUT OF THE SONSTRAINING INFLIENCE OF THE PETALS.

THE SHELL FRAGMENTS ARE ALMOST ALL COMMITTE Y THRITTEN HOLE. THE PETALS HAVE SURLED MADE TO PRICE PLANES FOR THE EACH STRUMBERTY ALL OF HISTORY ALEXANDERS.

THE PETELS WHITE INTERNETS TO LIFE, BALL TO THE STATE & WILLE SETTING THE THEFT & MIDES IN THE STATE OF THE S





High Speed X-Ray Pictures of the Functioning of 20 mm. H.E. Shell, MK-3 (Navy) When Fired Through a 1/8 in. Mild Steel Target Placed Normal to Line of Fire






FIGURE 19